Patent 7,618,462 PATENT

## IN UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 7,618,462 Docket No: STD00.01CIP2CON

Issue Date: November 17, 2009 Patentee: Steven W. Ek
Title SYSTEM AND METHOD FOR JOINT RESURFACE REPAIR

## REQUEST FOR CERTIFICATION OF CORRECTION

Attn: Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. One copy of the text of the Certificate in the suggested form is attached.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims as properly allowed, and re-examination is not required.

As the error is that of the Patent Office, it is believed that no fee is due.

Respectfully submitted,

**Customer Number: 32047** 

Tel. 603-668-6560

By /Edmund P. Pfleger/

Edmund P. Pfleger Reg. No.: 41,252

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,618,462

DATED : November 17, 2009

INVENTOR(S) : Steven W. Ek

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face page, in field (63), in column 1, under "Related U.S. Application Data", line 1, delete "Continuation-in-part" and insert - - Continuation - -, therefor.

On the face page, in column 2, under "Other Publications", line 2, after "Replacement" delete "or" and insert - - of - -, therefor.

MAILING ADDRESS OF SENDER:

PATENT NO. \_\_\_\_\_7,618,462\_\_

No. of additional copies



Intellevate P.O. Box 52050 Minneapolis, MN 55402